Antique per 13/1/2011

RTI 1 of 3

To,

Central Public Information Officer (CPIO)

Indian Statistical Institute

203, B. T. Road

Kolkata - 700 108

Subject: Request for Information w.r.t. Construction of Mess Building, (civil and allied works) in ISI campus at Delhi Centre.

1. Name: H. K. Sachdeva

2. Full postal address: 7/108, Malviya Nagar, New Delhi - 110017

3. Telephone number: 9871547182

4. Fax number:

5. E-mail: hk.sachdeva7@gmail.com

6. Profession: Civil Engineer

7. Identity of the person: Individual

8. Residential status: Resident of New Delhi

9. Nationality/Citizenship: Indian

10. Information required/sought:

- A. How many times did Dr. B.K. Rao from CBRI visit the site in the month of June and July 2012?
- B. Did Dr. B.K. Rao inspect the site on 28-6-2012? If yes, please supply copy of inspection report.
- C. How many drawings were supplied to him?
- D. Who has signed these drawings?
- E. Were these drawings were bearing certificate "good for construction"?
- F. As per conclusions and recommendations of Dr. B.K. Rao dated 21-7-2012 "unfinished first floor portion of the building should be completed as early as possible."
 - a. Did Engineer Civil order the contractor to complete the unfinished first floor portion as early as possible?
 - b. Did Head Delhi Center ISI order the contractor to complete the unfinished first floor portion as early as possible?
 - c. Did any of the authority order the contractor to complete the unfinished first floor portion as early as possible?
- G. Did Dr. B.K. Rao from CBRI Roorkee recommend demolition of new mess building (under construction) in part or whole? If yes, please supply the related document.

- H. Did Sh. Subhash C. Mukhopodhyay recommend demolition of new mess building (under construction) in part or whole? If yes, please supply the related document.
- I. Did architect recommend demolition of new mess building (under construction) in part or whole? If yes, please supply the related document.
- J. Did Engineer Civil Sh. V. Bandhu recommend demolition of new mess building (under construction) in part or whole? If yes, please supply the related document.
- K. Did Dr. R.B. Bapat recommend demolition of new mess building (under construction) in part or whole? If yes, please supply the related document.
- L. Did Sh. A.G. Bhatt recommend demolition of new mess building (under construction) in part or whole? If yes, please supply the related document.
- M. Did Sh. S.P. Das recommend demolition of new mess building (under construction) in part or whole? If yes, please supply the related document.
- N. Did Sh. T. Narayana Swamy recommend demolition of new mess building (under construction) in part or whole? If yes, please supply the related document.
- O. Who has recommended demolition of new mess building (under construction) in part or whole? Please supply the related document.
- P. Was Engineer Civil Sh. V. Bandhu asked to be present at site during the inspection done by Dr. B.K. Rao? If yes, please supply the related document.
- Q. Was architect called during the inspection by Dr. B.K. Rao? If yes, please supply the related document.
- R. Was any machine used for excavation?
 - a. If yes, please supply registration number of machine?
- S. How much money was paid to the owner of the machine used for excavation?
 - a. Please supply a copy of receipt of the payment made.

11. Signature of the applicant:

12. Place and Date: New Delhi, and Jan 8, 2014

1 VSLH00

13. Enclosure: Postal order no. 13F 873872