

Telephones: (033) 2577 6927 /

2575-2251

Fax

: +(91)(33) 2577 6033

E-mail

: ceaf@isical.ac.in



203 BARRACKPORE TRUNK ROAD KOLKATA 700 108, INDIA

> No.CAF/21-A/230/ 922 26 February, 2014

Shri H.K.Sachdeva 7/108, Malviya Nagar, New Delhi-110017

Dear Sir,

With reference to your RTI application dated 27.01.2014, received by the CPIO on 29.01.2014, the information, as sought for, are furnished below:-

Information sought		Information supplied
Ä.	Please supply copy of photographs taken on 6-07-2012 to check the foundation details in presence of CBRI personnel Dr. B.K. Rao (Please supply photographs of foundations only.	us, except CBRI's report containing
В.	Please supply copy of letter written by Head Delhi Centre / competent authority directing Engineer Civil Mr. V. Bandhu to hand over site order book, cement register, steel register, material at site register, test register, guard file, hindrance register etc.	Office Order dated 01.11.2011 enclosed.
C.	Please supply copy of letter issued by competent authority issued for searching site order book, cement register, steel register, material at site register, test register, guard file, hindrance register etc.	No record available.
D.	As per conclusions and recommendations of Dr. B. K. Rao CBRI (Please refer your letter no. CAF/21-A/164/599 dated 02 January, 2014)" In case, if the structure is found to be unsafe from the above mentioned proof checking, then appropriate repair retrofitting measures may be adopted to bring the structure safe and serviceable condition". Please supply copy of documents showing the appropriate repair retrofitting measures taken.	No record available.
E.	Please supply copy of letter(s) written to contractor by Head Delhi Centre/ competent authority that a committee named NMBCEC has been formed.	No record available.
F.	Please supply copy of letter(s) issued by competent authority directing Mr. V. Bandhu Engineer Civil / contractor to be available for inspection on 26-08-11.	No record available.

Please supply copy of inspection report signed by officers / Engineer civil who accompanied Mr. S. C. Mukhopadhyay on 26-08-2011.	Not applicable in view of answer to F.
When did this inspection party meet (name of the representative of the contractor M/S A2Z Constructions) at site on 26-8-2011.	No record available.
At what time this inspection was carried out on 26-08- 2011 by Mr. S. C. Mukhopadhyay and others?	No record available.
No steps have been taken to conduct load test as recommended by Mr. S. C. Mukhopadhyay. Please supply document which reveals that there was no need to conduct load test as recommended by Mr. S. C. Mukhopadhyay	No such document available.
Did Sh R.B. Bapat Head Delhi Centre approve the bills of contractor (RA1-RA7) after observing the fact that measurements / measurement book/ bills were signed by Sh. S S Sethi DCE (inchrge civil and electrical department)?	No document is being asked.
Did Sh A G Bhatt Head Delhi Centre approve the bills of contractor (RA1-RA7) after observing the fact that measurements / measurement book/ bills were signed by Sh. S S Sethi DCE (inchrge civil and electrical department)?	-do-
Sh S P Das Head Delhi Centre approve the bills of contractor (RA1-RA7) after observing the fact that measurements / measurement book/ bills were signed by Sh. S S Sethi DCE (inchrge civil and electrical department). Is this statement correct of not?	No reply is warranted.
Please refer your letter no. CAF/21-A/181/694 dated 20 January, 2014 as per which point no. 5, the information sought was "Is the structural design safe as per calculation submitted by Sh Chandra Pal". Please supply copy of letter through which same question was answered.	The reply to your RTI application dated 4.01.2014 was answered vide letter No. CAF/21-A/203/764(A) dated 6.02.2014 (Copy enclosed).
	officers / Engineer civil who accompanied Mr. S. C. Mukhopadhyay on 26-08-2011.  When did this inspection party meet (name of the representative of the contractor M/S A2Z Constructions) at site on 26-8-2011.  At what time this inspection was carried out on 26-08-2011 by Mr. S. C. Mukhopadhyay and others?  No steps have been taken to conduct load test as recommended by Mr. S. C. Mukhopadhyay. Please supply document which reveals that there was no need to conduct load test as recommended by Mr. S. C. Mukhopadhyay  Did Sh R.B. Bapat Head Delhi Centre approve the bills of contractor (RA1-RA7) after observing the fact that measurements / measurement book/ bills were signed by Sh. S S Sethi DCE (inchrge civil and electrical department)?  Did Sh A G Bhatt Head Delhi Centre approve the bills of contractor (RA1-RA7) after observing the fact that measurements / measurement book/ bills were signed by Sh. S S Sethi DCE (inchrge civil and electrical department)?  Sh S P Das Head Delhi Centre approve the bills of contractor (RA1-RA7) after observing the fact that measurements / measurement book/ bills were signed by Sh. S S Sethi DCE (inchrge civil and electrical department). Is this statement correct of not?  Please refer your letter no. CAF/21-A/181/694 dated 20 January, 2014 as per which point no. 5, the information sought was "Is the structural design safe as per calculation submitted by Sh Chandra Pal". Please supply copy of letter through which same

Your RTI application dated 27.01.2014, received by the CPIO on 29.01.2014, is disposed off. Prof. Bimal K. Roy, Director of the Institute at the above address is the Appellate Authority.

Prof. S. P. Das Head, Del hi Cutre Yours faithfully,

Central Public Information Officer